

Attachment A: Digital Images

Page 1 of 7

May 13th, 2008

BOE Building 20th Floor Break Room

Sacramento, CA



- 1) Image of entry to 20th Floor Break Room (2014) with BOE generated posting present on doorway at the time of BioMax's assessment.



- 2) Image of Break Room cabinet at time of preliminary inspection. Blue tape present on impacted cabinet material as applied by BOE staff prior to BioMax's inspection.



- 3) Image within cabinetry of Break Room upon removal of tape barrier. Note cracking and staining present on laminant cabinet base materials.



- 4) Close-up image of cracking and delamination within cabinet base materials. Note adjacent vinyl baseboard and tile flooring material delamination at time of assessment.



- 5) Image within sink cabinet of “Insta-hot” water treatment unit with staining along the rear vertical wall emanating from behind the noted unit.



- 6) Image of sink insert base and plumbing within cabinet base. Evidence of historical leaking at base of “S” trap evident at time of assessment.



- 7) Close-up image of Personal appliances storage within adjacent cabinet compartment at time of assessment.



- 8) Image of right side of cabinet at floor level. Evidence of historical water staining present on cabinet door, vinyl baseboard, and floor tile materials.



- 9) Image of air handling equipment utilized within break room and reference locations of existing furnishings where no evidence of moisture damages were noted at this time.



- 10) Image of Mr. Polkaba of BioMax collecting surface sample from representative material within break room not directly affected by moisture contact/release.



11) Image of occupied cubicle area adjacent to break room. Cubicle divider top frame in foreground served as a representative area for surface sampling and comparative analysis.



12) Image of air sampling activity performed within Nikkole Thom's cubicle area adjacent to (with shared rear wall) the break room.



13) Image of air sampling activity performed within hallway of occupied cubicle area adjacent to break room.



14) Image of air sampling activity performed within MAP Scanning room (#2013) adjacent to (with shared rear wall) the noted break room.